






Please double check the PIN number , depending if is male or female , rear view or front view can cause a lot of troubles.

DB15
CAT1 Expert 2K

DATA In STEPPIR



"Y" CABLE



TS-990 REAR